


RF MONITOR

PC supervision software



WIRELESS SENSOR NETWORK ON PC

Connect your Newsteo wireless sensors and display the measurements of all your sensors remotely on your computer.

▲ A SIMPLE AND EFFICIENT TOOL FOR YOUR SUPERVISION



- ✓ Visualization of all connected sensors
- ✓ Advanced functions for sorting measurements, creating graphs ...
- ✓ Settings done by radio



ASSETS



RF Monitor software allows you to deploy a wireless sensor network on a site at an unbeatable price.

Real-time traceability ...

- Visualization of measurements in real time
- Data transmission by radio
- Single site solution
- Ideal as part of a HACCP, GDP approach
- CFR21 part 11 Option

... Or on-board recording

- Recording campaign with downloading of measurements at the end of the campaign




Easy settings

- Measurement frequency
- Alert thresholds

Data storage on the PC

- All measurements are transmitted to the PC and stored in a local database
- The database includes advanced functions for sorting measurements, creating graphs ...
- Export data to CSV files (EXCEL compatible) and / or PDF reports.



ID	Description	Type	Status	Location	Batterie	Température	Humidité	Signal	Commentaire
1	LOG000146	LOG000146	OK	LOG000146	91.15%	20.0°C	60%	OK	
2	LOG000146	LOG000146	ALERT	LOG000146	91.15%	20.0°C	60%	ALERT	Température hors seuil
3	LOG000146	LOG000146	OK	LOG000146	91.15%	20.0°C	60%	OK	
4	LOG000146	LOG000146	OK	LOG000146	91.15%	20.0°C	60%	OK	
5	LOG000146	LOG000146	OK	LOG000146	91.15%	20.0°C	60%	OK	
6	LOG000146	LOG000146	OK	LOG000146	91.15%	20.0°C	60%	OK	
7	LOG000146	LOG000146	OK	LOG000146	91.15%	20.0°C	60%	OK	

Alerts

- Visual and audible alert when a device detects an out-of-threshold measurement
- Alert in case of transmission loss or low battery level